

JOB
Faucet Replacement
CUSTOMER
Jane Smith

LOCATION
123 Main Street, Nashville TN
TECHNICIAN
John Smith

DATE
March 22, 2026


REPORT ID IP-824625

Verify: <https://ironproof.app/verify/IP-824625>

Please review the following photo documentation and notes for the referenced project.

BEFORE

Photo 1 — Pre-Work Condition



Captured: Mar 22, 2026, 10:01 PM UTC

' Verified Hash: f3a70e1d...

Existing faucet

Photo 2 — Pre-Work Condition




Captured: Mar 22, 2026, 10:01 PM UTC

' Verified Hash: b56ff5b1...

No caption

Photo 3 — Pre-Work Condition



Captured: Mar 22, 2026, 10:01 PM UTC

' Verified Hash: 2dfe9e28...

Under sink conditions

Photo 4 — Pre-Work Condition



Captured: Mar 22, 2026, 10:02 PM UTC

' Verified Hash: 355bf198...

Existing plumbing connections

DURING

Photo 1 — Work In Progress




Captured: Mar 22, 2026, 10:37 PM UTC

' Verified Hash: a4072b60...

Under sink after faucet removal

Photo 2 — Work In Progress




Captured: Mar 22, 2026, 10:38 PM UTC

' Verified Hash: 9bcf65b9...

Faucet has been removed

Photo 3 — Work In Progress




Captured: Mar 22, 2026, 10:38 PM UTC

' Verified Hash: 174c5b5d...

Sink area after faucet removal

Photo 4 — Work In Progress



Captured: Mar 22, 2026, 10:46 PM UTC

' Verified Hash: 0f48125b...

No caption

Photo 5 — Work In Progress




Captured: Mar 22, 2026, 11:27 PM UTC

' Verified Hash: 0ccb18fb...

Work area cleaned prior to new faucet installation

AFTER

Photo 1 — Completed Work



Captured: Mar 22, 2026, 11:28 PM UTC

' Verified Hash: 53ed9825...

New faucet installed

Photo 2 — Completed Work



Captured: Mar 22, 2026, 11:28 PM UTC

' Verified Hash: 23435fc0...

No caption

Photo 3 — Completed Work



Captured: Mar 22, 2026, 11:28 PM UTC

' Verified Hash: 1151a9a8...

Under sink conditions after faucet swap

Photo 4 — Completed Work




Captured: Mar 22, 2026, 11:28 PM UTC

' Verified Hash: 2befb2cd...

New plumbing connections after swap

Photo 5 — Completed Work



Captured: Mar 22, 2026, 11:28 PM UTC

' Verified Hash: fdd51896...

Water runs normally

FIELD NOTES

This faucet replacement went smoothly. Area was cleaned up after work and the new faucet works great.

Verification Statement

All photos include visible timestamps and are cryptographically hashed upon server upload. SHA-256 integrity verification confirms no post-capture alterations.